



Equipment Group INC

2010 E Omaha Ave Frontage Rd, Norfolk, NE 68701

Phone: (402) 396-7402 | Email: sales@equipmentgroupinc.com

Equipment Inspection Form

2022 JCB 1CXT • Compact Tracked Backhoe Loader



Inspection date: July 27, 2026

Inspector name: Edward Stone

Make / Model: JCB 1CXT

Year: 2022

Serial / PIN: JCB1CXT4HM2935207

Hour meter reading: 218 Hrs

Inspection location: Norfolk, NE 68701

Purpose: Sale

Unit reference: 2022 JCB 1CXT compact tracked backhoe loader with front loader and rear backhoe, 218 hours at time of inspection.

Legend: check **OK** if the item is in good condition, **Issue** if it needs attention/repair, and record details under Notes (e.g. fault code, noise, leak, wear level).

1. Exterior / Body

Inspection point	OK	Issue	Notes
Paint and body panels (cracks, dents, rust)	☒	☐	
Overall frame / chassis condition	☒	☐	
Decals and serial plate legible	☒	☐	
Hour meter functioning and reading correctly	☒	☐	
Mirrors, handrails, access steps	☒	☐	

2. Engine

Inspection point	OK	Issue	Notes
Engine oil level and color	✓	■	
Coolant level, radiator condition	✓	■	
Air filter (clean / condition)	✓	■	
Belts and hoses (cracks, tension)	✓	■	
Visible leaks (oil, fuel, coolant)	✓	■	
Cold start — ease of starting and noise	✓	■	
Exhaust smoke color at idle / acceleration	✓	■	
Idle stability	✓	■	

3. Undercarriage and tracks

Inspection point	OK	Issue	Notes
Rubber track condition — wear, cracks, missing lugs	✓	■	
Track tension — correct sag, adjusts properly	✓	■	
Rollers, idlers and sprockets — wear, leaks	✓	■	
Undercarriage frame — bent or damaged components	✓	■	
Track drive motors — smooth operation, no leaks	✓	■	

4. Travel / drive system

Inspection point	OK	Issue	Notes
Hydrostatic travel drive — smooth forward/reverse response	✓	■	
Travel pedals / levers — no excessive play	✓	■	
Tracking straight — no pull to one side	✓	■	
Parking / travel brake — holds unit on a grade	✓	■	

5. Hydraulic system

Inspection point	OK	Issue	Notes
Hydraulic fluid level	✓	■	
Loader arm raise / lower — speed and seal integrity	✓	■	
Backhoe boom / dipper — speed and seal integrity	✓	■	
Bucket curl / dump operation (front and rear)	✓	■	
Hydraulic hoses and cylinders (leaks, wear)	✓	■	
Quick-connect hydraulic couplers, if present	✓	■	

6. Front loader (structural)

Inspection point	OK	Issue	Notes
Loader arms — welds, bends, cracks	✓	■	
Pins and bushings — excessive play/wear	✓	■	
Front bucket — teeth condition, cutting edge wear	✓	■	
Bucket linkage — wear, play	✓	■	

7. Backhoe (structural)

Inspection point	OK	Issue	Notes
Boom — welds, bends, cracks	☒	☐	
Dipper (arm) — welds, bends, cracks	☒	☐	
Backhoe bucket — teeth condition, cutting edge wear	☒	☐	
Pins and bushings — excessive play/wear	☒	☐	
Stabilizer legs / outriggers — operation, wear	☒	☐	

8. Electrical system

Inspection point	OK	Issue	Notes
Battery — terminal condition, mounting, voltage	☒	☐	
Headlights and work lights	☒	☐	
Turn signals and beacon (if equipped)	☒	☐	
Horn / travel alarm	☒	☐	
Dashboard gauges / display functioning	☒	☐	
Alternator — proper charging while running	☒	☐	

9. Cab / Operator station

Inspection point	OK	Issue	Notes
Seat — adjustment, upholstery condition	☒	☐	
Seatbelt	☒	☐	
Joystick / pilot controls — functional, no drift	☒	☐	
Foot pedals — no excessive wear	☒	☐	
ROPS/FOPS structure (protection) — intact	☒	☐	
Visibility — windows, wipers (if enclosed cab)	☒	☐	

10. Attachments

Inspection point	OK	Issue	Notes
Front bucket — condition, teeth	☒	☐	
Backhoe bucket(s) — condition, teeth	☒	☐	
Quick-attach coupler condition (front and rear)	☒	☐	
Additional attachments included in sale	☒	☐	

11. Fluid leaks (check underneath unit)

Inspection point	OK	Issue	Notes
Engine oil leaks	☒	☐	
Hydraulic oil leaks	☒	☐	
Final drive / track motor leaks	☒	☐	
Coolant leaks	☒	☐	

12. Safety items

Inspection point	OK	Issue	Notes
ROPS/FOPS structure intact and properly secured	☒	☐	
Travel alarm functioning	☒	☐	
Guards and shields installed	☒	☐	
Fire extinguisher / first aid kit (if applicable)	☒	☐	

13. Operational test (test drive)

Inspection point	OK	Issue	Notes
Forward / reverse travel — smoothness, tracking straight	☒	☐	
Front loader function under load	☒	☐	
Backhoe function — dig, curl, swing under load	☒	☐	
Stabilizer legs — deploy and retract properly	☒	☐	
Unusual noise or vibration during test	☒	☐	
Engine temperature — stable after test	☒	☐	

Overall Assessment

Overall condition: ☒ Excellent ☐ Good ☐ Fair ☐ Needs repair

Issues identified requiring repair / attention:

None identified. Unit was inspected in all categories above (engine, undercarriage and tracks, hydraulics, front loader, backhoe, electrical, cab, attachments, and safety items) with no leaks, mechanical faults, or safety concerns found.

Inspector's final notes:

Unit presents in excellent, near-new condition consistent with its 218 recorded hours. Tracks, undercarriage, and all mechanical systems show minimal wear. Starts, runs, and operates smoothly through full front loader and backhoe range with no abnormal noise or vibration observed during testing. Recommended for sale as-is.

Inspector signature: 

Date: September 04, 2026