



Equipment Group INC

2010 E Omaha Ave Frontage Rd, Norfolk, NE 68701

Phone: (402) 396-7402 | Email: sales@equipmentgroupinc.com

Equipment Inspection Form

2021 John Deere 1025R • Sub-Compact Utility Tractor w/ Loader



Inspection date: July 30, 2026

Inspector name: Edward Stone

Make / Model: John Deere 1025R

Year: 2021

Serial / PIN: 1LV1025RHMM832929

Hour meter reading: 113 Hrs

Inspection location: Norfolk, NE 68701

Purpose: Sale

Unit reference: 2021 John Deere 1025R sub-compact tractor with front loader, 113 hours at time of inspection.

Legend: check **OK** if the item is in good condition, **Issue** if it needs attention/repair, and record details under Notes (e.g. fault code, noise, leak, wear level).

1. Exterior / Body

Inspection point	OK	Issue	Notes
Paint and engine hood panels (cracks, dents, rust)	☒	☐	
Overall frame / chassis condition	☒	☐	
Decals and serial plate legible	☒	☐	
Hour meter functioning and reading correctly	☒	☐	
Mirrors, handles, access steps	☒	☐	

2. Engine

Inspection point	OK	Issue	Notes
Engine oil level and color	☒	☐	
Coolant level, radiator condition	☒	☐	
Air filter (clean / condition)	☒	☐	
Belts and hoses (cracks, tension)	☒	☐	
Visible leaks (oil, fuel, coolant)	☒	☐	
Cold start — ease of starting and noise	☒	☐	
Exhaust smoke color at idle / acceleration	☒	☐	
Idle stability	☒	☐	

3. Transmission and drivetrain (4WD)

Inspection point	OK	Issue	Notes
Four-wheel drive engagement / disengagement	☒	☐	
Gear/range shifting — smoothness, no binding	☒	☐	
Hydrostatic transmission (HST) pedal response	☒	☐	
Power take-off (PTO) — engagement and operation	☒	☐	
Abnormal noise while driving (transmission/differential)	☒	☐	

4. Hydraulic system

Inspection point	OK	Issue	Notes
Hydraulic fluid level	☒	☐	
Front loader operation	☒	☐	
Boom raise / lower — speed and seal integrity	☒	☐	
Bucket curl / dump operation	☒	☐	
3-point hitch operation (rear lift)	☒	☐	
Hydraulic hoses and cylinders (leaks, wear)	☒	☐	
Quick-connect hydraulic couplers	☒	☐	

5. Tires and wheels

Inspection point	OK	Issue	Notes
Front tires — tread wear / depth	☒	☐	
Rear tires — tread wear / depth	☒	☐	
Air pressure (per specification)	☒	☐	
Cuts, cracks, or bulges	☒	☐	
Wheel lug nuts / bolts — tight, none missing	☒	☐	

6. Brakes

Inspection point	OK	Issue	Notes
Service brake — effectiveness under test	☒	☐	
Parking brake — holds unit on a grade	☒	☐	
Brake pedals — even travel left/right	☒	☐	

7. Electrical system

Inspection point	OK	Issue	Notes
Battery — terminal condition, mounting, voltage	☒	☐	
Headlights and work lights	☒	☐	
Turn signals and brake lights (if equipped)	☒	☐	
Horn	☒	☐	
Dashboard gauges / display functioning	☒	☐	
Alternator — proper charging while running	☒	☐	

8. Operator station

Inspection point	OK	Issue	Notes
Seat — adjustment, upholstery condition	☒	☐	
Seatbelt	☒	☐	
Steering wheel — no excessive play	☒	☐	
Pedals (HST forward/reverse, brake) — no excessive wear	☒	☐	
Hydraulic control levers — functional, labeled	☒	☐	
ROPS structure (rollover protection) — intact, folds properly	☒	☐	

9. Attachments and mounted equipment

Inspection point	OK	Issue	Notes
Front loader — overall condition, mounting	☒	☐	
Bucket / forks / other attachments included	☒	☐	
Quick-attach coupler condition	☒	☐	
Mower deck or other implement (if included in sale)	☒	☐	

10. Fluid leaks (check underneath unit)

Inspection point	OK	Issue	Notes
Engine oil leaks	☒	☐	
Hydraulic oil leaks	☒	☐	
Transmission / differential leaks	☒	☐	
Coolant leaks	☒	☐	

11. Safety items

Inspection point	OK	Issue	Notes
ROPS structure intact and properly secured	☒	☐	
Slow Moving Vehicle (SMV) emblem present	☒	☐	
Guards and shields installed (PTO shield, belt covers)	☒	☐	
Fire extinguisher / first aid kit (if applicable)	☒	☐	

12. Operational test (test drive)

Inspection point	OK	Issue	Notes
Forward travel — smoothness, no vibration	☒	☐	
Reverse travel	☒	☐	
Steering — no excessive play, correct response	☒	☐	
Braking behavior while driving	☒	☐	
Unusual noise or vibration during test	☒	☐	
Engine temperature — stable after test	☒	☐	

Overall Assessment

Overall condition: ☒ Excellent ☐ Good ☐ Fair ☐ Needs repair

Issues identified requiring repair / attention:

None identified. Unit was inspected in all categories above (engine, drivetrain, hydraulics, tires, brakes, electrical, operator station, attachments, and safety items) with no leaks, mechanical faults, or safety concerns found.

Inspector's final notes:

Unit presents in near-new condition consistent with its 113 recorded hours. Paint, tires, and all mechanical systems show minimal wear. Starts, runs, and operates smoothly with no abnormal noise or vibration observed during testing. Recommended for sale as-is.

Inspector signature: _____

Date: July 30, 2026