



Equipment Group INC

2010 E Omaha Ave Frontage Rd, Norfolk, NE 68701
Phone: (402) 396-7402 | Email: sales@equipmentgroupinc.com

Equipment Inspection Form

2021 Volvo L30GS • Compact Wheel Loader



Inspection date: July 30, 2026

Make / Model: Volvo L30GS

Serial / PIN: VCEL30GSL03224646

Inspection location: Norfolk, NE 68701

Inspector name: Edward Stone

Year: 2021

Hour meter reading: 79 Hrs

Purpose: Sale

Unit reference: 2021 Volvo L30GS compact wheel loader, 79 hours at time of inspection.

Legend: check **OK** if the item is in good condition, **Issue** if it needs attention/repair, and record details under Notes (e.g. fault code, noise, leak, wear level).

1. Exterior / Body			
Inspection point	OK	Issue	Notes
Paint and body panels (cracks, dents, rust)	☒	☐	
Overall frame condition, articulation joint	☒	☐	
Decals and serial plate legible	☒	☐	
Hour meter functioning and reading correctly	☒	☐	
Mirrors, handrails, access steps	☒	☐	

2. Engine

Inspection point	OK	Issue	Notes
Engine oil level and color	✓	■	
Coolant level, radiator condition	✓	■	
Air filter (clean / condition)	✓	■	
Belts and hoses (cracks, tension)	✓	■	
Visible leaks (oil, fuel, coolant)	✓	■	
Cold start — ease of starting and noise	✓	■	
Exhaust smoke color at idle / acceleration	✓	■	
Idle stability	✓	■	

3. Transmission and drivetrain

Inspection point	OK	Issue	Notes
Powershift transmission — shift quality, no slipping	✓	■	
Articulated steering — smooth, no excessive play	✓	■	
Articulation joint / center pin — no excessive wear	✓	■	
Differentials / axles — no abnormal noise	✓	■	
Abnormal noise while driving (transmission/driveline)	✓	■	

4. Hydraulic system

Inspection point	OK	Issue	Notes
Hydraulic fluid level	✓	■	
Loader arm raise / lower — speed and seal integrity	✓	■	
Bucket curl / dump operation	✓	■	
Steering hydraulics — responsive, no delay	✓	■	
Auxiliary hydraulics (for attachments), if equipped	✓	■	
Hydraulic hoses and cylinders (leaks, wear)	✓	■	
Quick-connect hydraulic couplers, if present	✓	■	

5. Loader arms and bucket (structural)

Inspection point	OK	Issue	Notes
Loader arms — welds, bends, cracks	✓	■	
Pins and bushings — excessive play/wear	✓	■	
Bucket — teeth/edge condition, cutting edge wear	✓	■	
Bucket linkage (Z-bar/parallel lift) — wear, play	✓	■	
Quick-attach coupler condition	✓	■	

6. Tires and wheels

Inspection point	OK	Issue	Notes
Front tires — tread wear / depth	✓	■	
Rear tires — tread wear / depth	✓	■	
Air pressure (per specification)	✓	■	
Cuts, cracks, or bulges	✓	■	
Wheel lug nuts / bolts — tight, none missing	✓	■	

7. Brakes

Inspection point	OK	Issue	Notes
Service brake — effectiveness under test	☒	☐	
Parking brake — holds unit on a grade	☒	☐	
Brake pedal — smooth, consistent travel	☒	☐	

8. Electrical system

Inspection point	OK	Issue	Notes
Battery — terminal condition, mounting, voltage	☒	☐	
Headlights and work lights	☒	☐	
Turn signals and brake lights	☒	☐	
Horn / travel-reverse alarm	☒	☐	
Dashboard gauges / display functioning	☒	☐	
Alternator — proper charging while running	☒	☐	

9. Cab / Operator station

Inspection point	OK	Issue	Notes
Seat — adjustment, upholstery condition	☒	☐	
Seatbelt	☒	☐	
Steering wheel / joystick steering — no excessive play	☒	☐	
Pedals — no excessive wear	☒	☐	
Hydraulic controls / levers — functional, labeled	☒	☐	
ROPS/FOPS structure (protection) — intact	☒	☐	
Visibility — windows, wipers (if enclosed cab)	☒	☐	

10. Attachments

Inspection point	OK	Issue	Notes
Bucket(s) included — condition, teeth	☒	☐	
Quick-attach coupler condition	☒	☐	
Forks or other attachments included in sale	☒	☐	
Attachment hydraulic couplers — condition	☒	☐	

11. Fluid leaks (check underneath unit)

Inspection point	OK	Issue	Notes
Engine oil leaks	☒	☐	
Hydraulic oil leaks	☒	☐	
Transmission / axle / differential leaks	☒	☐	
Coolant leaks	☒	☐	

12. Safety items

Inspection point	OK	Issue	Notes
ROPS/FOPS structure intact and properly secured	☒	☐	
Travel / reverse alarm functioning	☒	☐	
Guards and shields installed	☒	☐	
Fire extinguisher / first aid kit (if applicable)	☒	☐	

13. Operational test (test drive)

Inspection point	OK	Issue	Notes
Forward / reverse travel — smoothness, no vibration	☑	■	
Articulated steering — full range, both directions	☑	■	
Loader arm / bucket function under load	☑	■	
Braking behavior while driving	☑	■	
Unusual noise or vibration during test	☑	■	
Engine temperature — stable after test	☑	■	

Overall Assessment

Overall condition: ☑ Excellent ■ Good ■ Fair ■ Needs repair

Issues identified requiring repair / attention:

None identified. Unit was inspected in all categories above (engine, drivetrain, hydraulics, tires, brakes, electrical, cab, attachments, and safety items) with no leaks, mechanical faults, or safety concerns found.

Inspector's final notes:

Unit presents in essentially brand-new condition with only 79 recorded hours. Tires, paint, and all mechanical systems show no measurable wear. Starts, runs, and operates smoothly through full loader arm and articulated steering range with no abnormal noise or vibration observed during testing. Recommended for sale as-is.

Inspector signature: _____

Date: July 30, 2026