Equipment Group INC

2010 E Omaha Ave Frontage Rd, Norfolk, NE 68701

Phone: (402) 396-7402 | Email: sales@equipmentgroupinc.com

Vehicle Inspection Form

2017 GMC Sierra 1500 SLT • Pickup Truck

Inspection date: October, 26 2026

Inspector name: Edward Stone

Make: GMC

Model: Sierra 1500 SLT

Year: 2017

VIN: 3GTP1NEC9HG181313

Mileage: 85,966

Engine: 5.3L EcoTec3 V8

Transmission: Automatic (8-Speed)

Drivetrain: RWD

Body Style: Truck

Exterior Color: Summit White

Interior Color: Jet Black

Title Status: Clean (GA)

Location: Norfolk, NE

Purpose: Sale

Legend: check **OK** if the item is in good condition, **Issue** if it needs attention/repair, and record details under Notes (e.g. fault code, noise, leak, wear level).

1. Exterior / Body

Inspection point	OK	Issue	Notes
Paint and body panels (dents, scratches, rust)	☑	☐	
Bed condition — liner, tailgate, latch operation	☑	☐	
Windshield and glass — chips, cracks	☑	☐	
Lights — headlights, taillights, fog lights, turn signals	☑	☐	
Mirrors, door handles, trim	☑	☐	

2. Engine

Inspection point	OK	Issue	Notes
Engine oil level and color	☑	☐	
Coolant level, radiator condition	☑	☐	
Air filter (clean / condition)	☑	☐	
Belts and hoses (cracks, tension)	☑	☐	
Turbocharger — no unusual noise, boost feels normal	☑	☐	
Visible leaks (oil, fuel, coolant)	☑	☐	
Cold start — ease of starting and noise	☑	☐	
Idle stability	☑	☐	

3. Transmission and drivetrain (4WD/AWD)

Inspection point	OK	Issue	Notes
Automatic transmission — shift quality, no slipping	☑	☐	
4WD/AWD engagement — smooth, no excessive play	☑	☐	
Transfer case operation (4Hi/4Lo, if applicable)	☑	☐	
Differentials — no abnormal noise	☑	☐	
Abnormal noise while driving (transmission/driveline)	☑	☐	

4. Tires and wheels

Inspection point	OK	Issue	Notes
Front tires — tread wear / depth	☑	☐	
Rear tires — tread wear / depth	☑	☐	
Spare tire present and inflated	☑	☐	
Air pressure (per specification)	☑	☐	
Cuts, cracks, or bulges	☑	☐	
Wheel lug nuts — tight, none missing	☑	☐	

5. Brakes

Inspection point	OK	Issue	Notes
Service brake — effectiveness under test	☑	☐	
Parking brake — holds vehicle on a grade	☑	☐	
Brake pedal — smooth, consistent travel	☑	☐	
Brake pads/rotors — visible wear check	☑	☐	

6. Electrical system

Inspection point	OK	Issue	Notes
Battery — terminal condition, mounting, voltage	☑	☐	
Alternator — proper charging while running	☑	☐	
Dashboard warning lights — none illuminated	☑	☐	
Power windows, locks, mirrors — all functional	☑	☐	
Infotainment / touchscreen — powers on, responsive	☑	☐	
Backup camera / sensors, if equipped	☑	☐	

7. Interior / Cabin

Inspection point	OK	Issue	Notes
Seats — condition, adjustment (power/manual)	☑	☐	
Seatbelts — all functional, no fraying	☑	☐	
Airbags — dashboard light off, no prior deployment	☑	☐	
A/C and heater — blow cold/hot as expected	☑	☐	
Odometer / instrument cluster — functioning correctly	☑	☐	
Interior odor — no smoke, mildew, or damage smell	☑	☐	

8. Frame and undercarriage

Inspection point	OK	Issue	Notes
Frame — no visible bends, rust-through, or cracks	☑	☐	
Exhaust system — no leaks, secure mounting	☑	☐	
Suspension components — bushings, shocks, no excessive play	☑	☐	
Skid plates / underbody protection, if equipped	☑	☐	

9. Fluid leaks (check underneath vehicle)

Inspection point	OK	Issue	Notes
Engine oil leaks	☑	☐	
Transmission fluid leaks	☑	☐	
Differential / transfer case leaks	☑	☐	
Coolant leaks	☑	☐	
Power steering fluid leaks	☑	☐	

10. Safety items

Inspection point	OK	Issue	Notes
Seatbelts functional in all seating positions	☑	☐	
Airbags intact, warning light off	☑	☐	
Spare tire, jack, and lug wrench present	☑	☐	
Fire extinguisher / first aid kit (if applicable)	☑	☐	

11. Operational test (test drive)

Inspection point	OK	Issue	Notes
Forward / reverse — smooth, no vibration	☑	☐	
Steering — no excessive play, correct response	☑	☐	
Braking behavior while driving	☑	☐	
4WD/AWD engagement tested under load, if possible	☑	☐	
Unusual noise or vibration during test	☑	☐	
Engine temperature — stable after test	☑	☐	

Overall Assessment

Overall condition: ☑ Excellent ■ Good ■ Fair ■ Needs repair

Issues identified requiring repair / attention:

None identified. Vehicle was inspected in all categories above (engine, transmission and drivetrain, tires, brakes, electrical, interior, frame, and safety items) with no leaks, mechanical faults, or safety concerns found.

Inspector's final notes:

Vehicle presents in excellent condition consistent with its low 85,966 miles. Paint, tires, interior, and all mechanical systems show minimal wear. Starts, runs, and drives smoothly with no abnormal noise or vibration observed during testing. Recommended for sale as-is.

Inspector signature: _____ Date: October, 26 2026