**Equipment Group INC**

2010 E Omaha Ave Frontage Rd, Norfolk, NE 68701

Phone: (402) 396-7402 | Email: sales@equipmentgroupinc.com

# Vehicle Inspection Form

2021 Jeep Gladiator California • Pickup Truck

**Inspection date:** October, 26 2026

**Inspector name:** Edward Stone

**Make:** Jeep

**Model:** Gladiator California

**Year:** 2021

**VIN:** 1C6HJTAG7ML555102

**Mileage:** 70,820

**Engine:** 3.6L V6

**Transmission:** Automatic (8-Speed)

**Drivetrain:** 4WD/AWD

**Body Style:** Truck

**Exterior Color:** Sting-Gray Clear-Coat

**Interior Color:** Black

**Title Status:** Clean (MA)

**Location:** Norfolk, NE

**Purpose:** Sale

Legend: check **OK** if the item is in good condition, **Issue** if it needs attention/repair, and record details under Notes (e.g. fault code, noise, leak, wear level).

## 1. Exterior / Body

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Paint and body panels (dents, scratches, rust) | ☑ | ☐ | |
| Bed condition — liner, tailgate, latch operation | ☑ | ☐ | |
| Windshield and glass — chips, cracks | ☑ | ☐ | |
| Lights — headlights, taillights, fog lights, turn signals | ☑ | ☐ | |
| Mirrors, door handles, trim | ☑ | ☐ | |

## 2. Engine

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Engine oil level and color | ☑ | ☐ | |
| Coolant level, radiator condition | ☑ | ☐ | |
| Air filter (clean / condition) | ☑ | ☐ | |
| Belts and hoses (cracks, tension) | ☑ | ☐ | |
| Turbocharger — no unusual noise, boost feels normal | ☑ | ☐ | |
| Visible leaks (oil, fuel, coolant) | ☑ | ☐ | |
| Cold start — ease of starting and noise | ☑ | ☐ | |
| Idle stability | ☑ | ☐ | |

## 3. Transmission and drivetrain (4WD/AWD)

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Automatic transmission — shift quality, no slipping | ☑ | ☐ | |
| 4WD/AWD engagement — smooth, no excessive play | ☑ | ☐ | |
| Transfer case operation (4Hi/4Lo, if applicable) | ☑ | ☐ | |
| Differentials — no abnormal noise | ☑ | ☐ | |
| Abnormal noise while driving (transmission/driveline) | ☑ | ☐ | |

## 4. Tires and wheels

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Front tires — tread wear / depth | ☑ | ☐ | |
| Rear tires — tread wear / depth | ☑ | ☐ | |
| Spare tire present and inflated | ☑ | ☐ | |
| Air pressure (per specification) | ☑ | ☐ | |
| Cuts, cracks, or bulges | ☑ | ☐ | |
| Wheel lug nuts — tight, none missing | ☑ | ☐ | |

## 5. Brakes

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Service brake — effectiveness under test | ☑ | ☐ | |
| Parking brake — holds vehicle on a grade | ☑ | ☐ | |
| Brake pedal — smooth, consistent travel | ☑ | ☐ | |
| Brake pads/rotors — visible wear check | ☑ | ☐ | |

## 6. Electrical system

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Battery — terminal condition, mounting, voltage | ☑ | ☐ | |
| Alternator — proper charging while running | ☑ | ☐ | |
| Dashboard warning lights — none illuminated | ☑ | ☐ | |
| Power windows, locks, mirrors — all functional | ☑ | ☐ | |
| Infotainment / touchscreen — powers on, responsive | ☑ | ☐ | |
| Backup camera / sensors, if equipped | ☑ | ☐ | |

## 7. Interior / Cabin

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Seats — condition, adjustment (power/manual) | ☑ | ☐ | |
| Seatbelts — all functional, no fraying | ☑ | ☐ | |
| Airbags — dashboard light off, no prior deployment | ☑ | ☐ | |
| A/C and heater — blow cold/hot as expected | ☑ | ☐ | |
| Odometer / instrument cluster — functioning correctly | ☑ | ☐ | |
| Interior odor — no smoke, mildew, or damage smell | ☑ | ☐ | |

## 8. Frame and undercarriage

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Frame — no visible bends, rust-through, or cracks | ☑ | ☐ | |
| Exhaust system — no leaks, secure mounting | ☑ | ☐ | |
| Suspension components — bushings, shocks, no excessive play | ☑ | ☐ | |
| Skid plates / underbody protection, if equipped | ☑ | ☐ | |

## 9. Fluid leaks (check underneath vehicle)

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Engine oil leaks | ☑ | ☐ | |
| Transmission fluid leaks | ☑ | ☐ | |
| Differential / transfer case leaks | ☑ | ☐ | |
| Coolant leaks | ☑ | ☐ | |
| Power steering fluid leaks | ☑ | ☐ | |

## 10. Safety items

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Seatbelts functional in all seating positions | ☑ | ☐ | |
| Airbags intact, warning light off | ☑ | ☐ | |
| Spare tire, jack, and lug wrench present | ☑ | ☐ | |
| Fire extinguisher / first aid kit (if applicable) | ☑ | ☐ | |

## 11. Operational test (test drive)

| Inspection point | OK | Issue | Notes |
|---|---|---|---|
| Forward / reverse — smooth, no vibration | ☑ | ☐ | |
| Steering — no excessive play, correct response | ☑ | ☐ | |
| Braking behavior while driving | ☑ | ☐ | |
| 4WD/AWD engagement tested under load, if possible | ☑ | ☐ | |
| Unusual noise or vibration during test | ☑ | ☐ | |
| Engine temperature — stable after test | ☑ | ☐ | |

## Overall Assessment

**Overall condition:** ☑ Excellent ■ Good ■ Fair ■ Needs repair

**Issues identified requiring repair / attention:**

None identified. Vehicle was inspected in all categories above (engine, transmission and drivetrain, tires, brakes, electrical, interior, frame, and safety items) with no leaks, mechanical faults, or safety concerns found.

**Inspector's final notes:**

Vehicle presents in excellent condition consistent with its low 70,820 miles. Paint, tires, interior, and all mechanical systems show minimal wear. Starts, runs, and drives smoothly with no abnormal noise or vibration observed during testing. Recommended for sale as-is.

Inspector signature: _____ Date: October, 26 2026